PROCEDURE:

CASTINGS & STRAPS:

- 1. Inspect and repair any imperfections, then fettle castings.
- 2. Using correct jigs, mark timber mounting holes to casting, centre punch and drill to 3/8.
- 3. Drill and countersink fixing hole for pipe brace in end castings to 7/16 and counter sink to 11/16.
- 4. Drill 5/16 hole for the angled brace to fix to end castings, the hole is central in end castings (see sheet 3)
- 3. Using correct jig, mark & drill straps to 9/32.
- 5. Using correct jig, mark & drill feet of castings to 7/16.
- 6. Using correct jig & dies bend 20x5 flat bar to create angled brace drill both ends to 5/16 before pressing brace.
- 7. Weld 3/8 nuts in both ends of pipe support for fixing to end castings clean and linish welds.
- 8. Weld angled brace to pipe support using correct jig.
- 9. Remove sharps and deburr holes.


TIMBERS:

1. Using correct jig,drill timber slat ends to 7/16.

ASSEMBLY:

- 1. Ensure you have all components.
- 2. Loosely bolt one timber to castings and stand upright.
- 3. Loosely bolt angled brace and pipe support in position.
- 3. Bolt remaining timbers in place.
- 4. Ensure table is square and timber gaps are uniform.
- 5. Tighten bolts.
- 6. Turn table upside down and using tek screws, fix straps in position, at equal distancing.
- 7. INSPECTION

ITEM	PART NUMBER	DESCRIPTION	QTY
	PART NUMBER	DESCRIPTION	QIT
1	WIPCASTGOV25	FIESTA TABLE END CASTING	2
2	RSCHS15NBM	PIPE 15NB STD WEIGHT, 1770 LG	1
3	RSFB20X5	M/S FLAT 20x5 1910 LG V BRACE	1
4	RSFB20X3	FLAT 20x3 740 LG TABLE STRAP	2
5	TIMCHA63X30X1800	TIMBER SLAT 63x30 1800 LG	10
6	PFIX0900029	TIMBER TEKS	20
7	PFIX0900008	COACH BOLT, 5/16" x 2" LG c/w NUT	20
8	PFIX0900107	3/8" COUNTERSUNK HEAD BOLT c/w NUT	2
9	PFIX090020	COUNTERSUNK HEAD BOLT 1/4 X 1" C/W NUT	2



#		DESCRIPTION		DATE	DRAWN	DRAWN DATE CHE		KED	CHECKED DATE	SCALE	A4
Iz	1	ORIGINAL DRAWING	DN	8.10.10	R.CRIGHTON	6.12.13				N/A	A4
/ISION	2	L PRODUCT REVIEW RBC 6.12.13		E		FIESTA TABLE					
	3					FURPHY		BOM, PROCEDURE & ASSEMBLY			
Ц Ц Ц Ц Ц	4							FFSA003012	REV.	SHEET	
	5				$+$ $^{\prime}$	FOUNDRY EST. 1864	-	Г	F3A003012	2	2 OF 3